

A80 Supra GR Heritage Parts List

2023/5/1

■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.
 ※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
1	69210-14110- **	69210-14130	HANDLE ASSY, FR DOOR OUTSIDE, RH	All	1	
2	69220-14110- **	69220-14140	HANDLE ASSY, FR DOOR OUTSIDE, LH	All	1	
3	44610-14860, 44610-14880, 44610-1B010	44610-14860	BOOSTER ASSY, BRAKE	part of USA model EUR model (LHD) GEN model (LHD)	1	USA model non-turbo
4	81130-1B160, 81130-1B250	81130-1B160	HEADLAMP UNIT ASSY, RH	Early model(Japan)	1	
5	81170-1B160, 81170-1B250	81170-1B160	HEADLAMP UNIT ASSY, LH	Early model(Japan)	1	
6	89465-19635	89465-19635	SENSOR, OXYGEN	Turbo early model(Japan)	1	
7	89465-19725	89465-19725	SENSOR, OXYGEN	Turbo early model(Japan)	1	
8	52119-14918 52119-14916	52119-14420	COVER, FR BUMPER L/COLOR	Japan early model European model	1	Drilling holes to a bumper is necessary.
9	52119-14927	52119-14430	COVER, FR BUMPER L/COLOR	Japan late model	1	Drilling holes to a bumper is necessary.
10	52119-14917	52119-14440	COVER, FR BUMPER L/COLOR	US early model	1	Drilling holes to a bumper is necessary.
11	69570-14060 69570-14070	69570-14070	CYLINDER ASSY, IGNITION SWITCH LOCK	JPN model	1	・In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase. ・Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently beina supplied.
12	69005-14750	69005-14750	CYLINDER & KEY SET	USA model (1996.07-1997.09) (Note)There is the compatibility with all models but some changes will happen to your vehicle. Please see the following note.	1	・(Note) It is also possible to replace the other USA models, JPN models and EUR models. At that time, if the vehicle is equipped with ignition key lighting, it will not be lit. ・The key number will be a new number. ・The following items are included in this set. (3 keys, ignition switch lock cylinder assembly, front door lock cylinder assembly RH, front door lock cylinder assembly LH, glove compartment door lock cylinder assembly and luggage compartment door lock cylinder ASSY) ・Purchase of separate cylinders is not available. ・ When replacing the luggage compartment door lock cylinder assembly It may not be possible to connect the connector on some vehicles with US specifications. In that case, please replace it according to the following procedure. 1) Remove the cylinder side connector attached to the vehicle. 2) Remove the cylinder side connector of the reprinted product and replace it with the connector removed in (1). 3) Connect to the connector on the vehicle side. If it is not connected to the connector on the vehicle side, security may sound when the door is unlocked.
13	69510-14110	69510-14110	CYLINDER ASSY, FR DOOR LOCK, RH	JPN model	1	・In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase. ・Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently beina supplied.

A80 Supra GR Heritage Parts List

2023/5/1

■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.
 ※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
14	69520-14100	69520-14100	CYLINDER ASSY, FR DOOR LOCK, LH	JPN model	1	・In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase. ・Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.
15	68131-14320	68131-14320	GLASS, BACK DOOR	USA model (1996.07-1998.08) Due to the different printed antenna pattern, it cannot be used in Japan. Japan model is currently supplied as 68131-14300-76 (as of June 2023).	1	・The background color is shown in the product image, but the glass color is green. ・As the part number differs depending on the destination, please purchase 68131-14320 when purchasing overseas, and 68131-14320-76 when purchasing in Japan.
16	84140-20540	84140-20540	SWITCH ASSY, HEADLAMP DIMMER	JPN model (1997.09-2002.08)	1	

■ Substitute Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
 ※GR Heritage Parts can be purchased at your nearest Toyota dealer, just like regular spare parts.
 ※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
1	44610-14850 44610-14870	44610-14850	BOOSTER ASSY, BRAKE	part of USA model EUR model (RHD) GEN model (RHD) part of JPN model	1	44610-14870 was substituted by this part due to fitment has been confirmed. USA model turbo JPN model (tire size) front 225/50ZR16 + rear 225/50ZR16 front 225/50ZR16 + rear 245/50ZR16 front 225/50ZR16 + rear 245/45ZR16 front 235/45ZR17 + rear 255/40ZR17 (-1996.05)
2	44610-14890	44610-14890	BOOSTER ASSY, BRAKE	part of JPN model	1	This part has been continuously supplied, not revival parts. JPN model (tire size) front 235/45ZR17 + rear 255/40ZR17 (1996.05-)
3	81111-1B230 81111-1B231	81111-1B231	HEADLAMP UNIT ASSY, RH	Late model(Japan)	1	81111-1B230 was substituted by this part due to fitment has been confirmed.
4	81151-1B230 81151-1B231	81151-1B231	HEADLAMP UNIT ASSY, LH	Late model(Japan)	1	81151-1B230 was substituted by this part due to fitment has been confirmed.
5	48610-19025	48610-29046	ARM ASSY SUSPENSION, RH	All models (1993.05-1996.05)	1	48610-19025 was substituted by this part due to fitment has been confirmed.
6	48630-19025	48630-29046	ARM ASSY SUSPENSION, LH	All models (1993.05-1996.05)	1	48630-19025 was substituted by this part due to fitment has been confirmed.