

A80 Supra GR Heritage Parts List

2025/10/1

■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
※GR Heritage Parts can be purchased at your nearest Toyota dealer,
just like regular spare parts.
※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
1	69210-14110-**	69210-14130	HANDLE ASSY, FR DOOR OUTSIDE, RH	All	1	
2	69220-14110-**	69220-14140	HANDLE ASSY, FR DOOR OUTSIDE, LH	All	1	
3	44610-14860, 44610-14880, 44610-1B010	44610-14860	BOOSTER ASSY, BRAKE	part of USA model EUR model (LHD) GEN model (LHD)	1	USA model non-turbo
4	81130-1B160, 81130-1B250	81130-1B160	HEADLAMP UNIT ASSY, RH	Early model(Japan)	1	
5	81170-1B160, 81170-1B250	81170-1B160	HEADLAMP UNIT ASSY, LH	Early model(Japan)	1	
6	89465-19635	89465-19635	SENSOR, OXYGEN	Turbo early model(Japan)	1	
7	89465-19725	89465-19725	SENSOR, OXYGEN	Turbo early model(Japan)	1	
8	52119-14918 52119-14916	52119-14420	COVER, FR BUMPER L/COLOR	Japan early model European model	1	Drilling holes to a bumper is necessary.
9	52119-14927	52119-14430	COVER, FR BUMPER L/COLOR	Japan late model	1	Drilling holes to a bumper is necessary.
10	52119-14917	52119-14440	COVER, FR BUMPER L/COLOR	US early model	1	Drilling holes to a bumper is necessary.
11	69570-14060 69570-14070	69570-14070	CYLINDER ASSY, IGNITION SWITCH LOCK	JPN model	1	<ul style="list-style-type: none"> • In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase. • Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.
12	69005-14750	69005-14750	CYLINDER & KEY SET	USA model (1996.07-1997.09)	1	<ul style="list-style-type: none"> • (Note) It is also possible to replace the other USA models, JPN models and EUR models. At that time, if the vehicle is equipped with ignition key lighting, it will not be lit. • The key number will be a new number. • The following items are included in this set. (3 keys, ignition switch lock cylinder assembly, front door lock cylinder assembly RH, front door lock cylinder assembly LH, glove compartment door lock cylinder assembly and luggage compartment door lock cylinder ASSY) • Purchase of separate cylinders is not available.
13	69510-14110	69510-14110	CYLINDER ASSY, FR DOOR LOCK, RH	JPN model	1	<ul style="list-style-type: none"> • When replacing the luggage compartment door lock cylinder assembly It may not be possible to connect the connector on some vehicles with US specifications. In that case, please replace it according to the following procedure. <ol style="list-style-type: none"> 1) Remove the cylinder side connector attached to the vehicle. 2) Remove the cylinder side connector of the reprinted product and replace it with the connector removed in (1). 3) Connect to the connector on the vehicle side. If it is not connected to the connector on the vehicle side, security may sound when the door is unlocked. • In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase. • Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.

A80 Supra GR Heritage Parts List

2025/10/1

■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.
※GR Heritage Parts can be purchased at your nearest Toyota dealer,
just like regular spare parts.
※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
14	69520-14100	69520-14100	CYLINDER ASSY, FR DOOR LOCK, LH	JPN model	1	<ul style="list-style-type: none"> •In Japan, available for purchase it with the same key number as other Toyota vehicles. Car key number is required at the time of purchase. •Glove box compartment door lock key cylinder ASSY and luggage compartment door lock key cylinder ASSY are currently being supplied.
15	68131-14320	68131-14320	GLASS, BACK DOOR	USA model (1996.07-1998.08) Due to the different printed antenna pattern, it cannot be used in Japan. Japan model is currently supplied as 68131-14300-76 (as of June 2023).	1	<ul style="list-style-type: none"> •The background color is shown in the product image, but the glass color is green. •As the part number differs depending on the destination, please purchase 68131-14320 when purchasing overseas, and 68131-14320-76 when purchasing in Japan.
16	84140-20540	84140-20540	SWITCH ASSY, HEADLAMP DIMMER	JPN model (1997.09-2002.08)	1	
17	44771-14010	44771-14010	HOSE, VACUUM TUBE CONNECTOR	JPN model EUR model RHD	1	
18	44774-14100	44774-14100	HOSE, UNION TO CONNECTOR TUBE	JPN model Turbo EUR model RHD	1	
19	23271-46150	23271-46150	HOSE, FUEL, NO.1(FOR RETURN TUBE, NO.1)	JPN model EUR model 199305-199605 USA model 199305-199709 USA model Turbo 199709-199808	1	
20	17341-46150	17341-46150	HOSE, AIR, NO.1(FOR INTERCOOLER)	JPN model Turbo EUR model Turbo 199305-199601 USA model Turbo 199305-199808	1	
21	17344-46030	17344-46030	HOSE, AIR, NO.4	JPN model Turbo EUR model Turbo 199305-199601 USA model Turbo 199305-199808	1	
22	55420-14030	55420-14030	PANEL ASSY, INSTRUMENT CLUSTER FINISH, CENTER	JPN model 199305-199605 EUR model RHD 199305-199601	1	
23	55420-14050	55420-14050	PANEL ASSY, INSTRUMENT CLUSTER FINISH, CENTER	JPN model 199605-	1	
24	89546-14020	89546-14020	SENSOR, SPEED, RR LH	JPN model (1996.05-) USA model (1996.07-1998.08)	1	RH spec (89545-14020) is available as of June 2024.
25	55410-14500	55410-14500	PANEL ASSY, INSTRUMENT CLUSTER FINISH	JPN model (1993.05-1996.05) EUR model RHD (1993.05-1996.01)	1	No indication [ODO/TRIP] and [RESET]. 
26	55410-14510	55410-14510	PANEL ASSY, INSTRUMENT CLUSTER FINISH	USA model (1993.05-1996.07) EUR model LHD (1993.05-1996.05)	1	No indication [ODO/TRIP] and [RESET]. 
27	55410-14520	55410-14520	PANEL ASSY, INSTRUMENT CLUSTER FINISH	JPN model (1996.05-)	1	
28	55404-14550	55404-14550	PANEL SUB-ASSY, INSTR CLUSTER FINISH	JZA80 RHD (199305-199605)	1	Vehicles without electric mirrors can have the cluster installed, but the hole in the switch area will remain open. The bezel around the key components is provided as a separate part in the package. Please assemble it yourself. 
29	55404-14560	55404-14560	PANEL SUB-ASSY, INSTR CLUSTER FINISH	JZA80 RHD (199605-200208)	1	Vehicles without electric mirrors can have the cluster installed, but the hole in the switch area will remain open. The bezel around the key components is provided as a separate part in the package. Please assemble it yourself. 
30	55405-14120	55405-14120	PANEL SUB-ASSY, INSTR CSTR FINISH, CTR	JZA80 JPN(199305-199605) JZA80 RHD GEN(199305-199408)	1	

A80 Supra GR Heritage Parts List

2025/10/1

■ Revival Parts(Genuine)



※Product design, specifications, and prices are subject to change without notice.

※GR Heritage Parts can be purchased at your nearest Toyota dealer,
just like regular spare parts.

※You can check the image of the parts from our HP.

No.	Original Part Number	Current Part Number	Part Name	Vehicle Application	Quantity per Unit	Note
31	55405-14160	55405-14160	PANEL SUB-ASSY, INSTR CSTR FINISH, CTR	JZA80 JPN(199605-)	1	
32	55420-14040	55420-14040	PANEL ASSY, INSTRUMENT CLUSTER FINISH, CENTER	JZA80..LHD(199305-199607)	1	
33	55404-14530	55404-14530	PANEL SUB-ASSY, INSTR CLUSTER FINISH	JZA80..LHD(199305-199607)	1	
34	89545-14010	89545-14010	SENSOR, SPEED, RR RH	JZA80 (199305-199607) with ABS	1	